

Pegler Valve

Ballofix isolating ballvalve, straight pattern. RP female ends, key lock and hexagon key operation, brass, plain finish



General Information

	Size	Pattern No.	Pack 1 Qty	Pack 2 Qty	Code	Barcode	Price (£) each ex VAT	Discontinued	D Disco	ate ntinued
1	/2"	3355BK	1	50	13219	5708537306545	£50.29			
3	3/4"	3455BK	5	50	13360	5708537306552	£65.99			
1	.1/2"	3755BK	1	0	13222	5708537403459	Disc(Stock available)	Discontinued	17/09/	2021
2	<u>'</u> "	3855BK	1	0	13223	5708537403398	Disc(Out of Stock)	Discontinued	17/09/	2021

Lockable isolating ball valve with key - straight pattern ball valve

Dimensions

Code Description A

13219 1/2 3355BK 57 0.23 13360 3/4 3455BK 62 0.36

Pegler Yorkshire reserve the right to change specifications

Guarantee

Pegler 5 Year Guarantee - Terms and Conditions

Products are subject to a 5 year guarantee that is between Pegler and the final purchaser of the product.

The guarantee is subject to proof of purchase being supplied.

This guarantee does not affect any statutory rights the consumer may have in law.

The guarantee covers manufacturing or material defects when installed in accordance with our instructions on specified tube materials and applications, and does not cover parts subject to normal wear and tear.

This product range has been designed for the use of homeowners, domestic and commercial applications and therefore the Guarantee is subject to the product being properly selected for their intended service conditions.

The guarantee is not applicable where the product is fitted contrary to the conditions in the fitting instructions.

This is reinforced where valves are covered by the European Pressure Equipment Directive (PED97/23/EC) where Installation, Operating and Maintenance Instructions are supplied with each product and/or carton.

Provided it is installed correctly and receives adequate preventative maintenance it should give years of trouble–free service.

Abusive behaviour and accidental damage to the product are not covered by this guarantee.

The extent of this liability is limited to the cost of the replacement of the defective item and not to installation or consequential damages.